



MITSUBISHI L200 (Triton) (KA; KB; 2.4; 2.5D; 3.2D)
MITSUBISHI Pajero Sport II (KH0; 2.5TD; 3.0; 3.2TD; 3.5)

2007
2008

14.3001

24/11/15

1/6





(GB) Location/Position Arrow











(GB) Movement Arrow






(GB) Screw Arrow



A			1X		
B	 M8x30	5X	C	 Ø 8	5X
D	 M10x30	2X	E	 Ø 10	2X
F		2X			
	14.3001		24/11/15	3/6	







5