SHERIFF www.karter.ru	Vehicle Model Model Year	Sportage 2,4 AT; 2,0 CRDi AT 2018~	Accessory Difficulty	Engine bay and transmission case (B)
Accessory Installation	Part No.	3957 MPE_3143 V4 MPE		
,	No	te: Difficulty stated above reflects the minimum (A)Customer (B)Dealer Te	level of expertise required to children (C) Master Techr	
nstructional Symbols / De	finitions			
Denotes warnings that may lead to serious physical injury or vehicle damage.		Denotes quality processes to be checked prior to moving to the next step.	Denotes safety equipment required to be used such as a mask, goggles, rubber gloves, and hearing protection.	
Denotes cautions to be ta injury or electronic compo		Denotes specific tools that are necessary to complete the step.		
			Mask	Goggles
Denotes cautions to be ta and component damage.	т	Denotes instructional steps necessary to complete the process.		
V	E		Rubber Gloves	Hearing Protection
Basic Required Hand Tools				

Screwdriver

Knife

Notes to the Installer :

Torque wrench

Tighten

-

Read the entire installation pamphlet prior to beginning the installation of the accessory.

Ensure that the vehicle is properly protected in the area that the accessory is to be installed.

To prevent vehicle damage, never place tools on top of painted surfaces, seats, dash pad, console or floor carpet / mat.


10 mm, 13mm, 17

mm


Always wear appropriate safety gear to include gloves and eye protection when required.

Ambient temperature of front body kit and vehicle must be 60°F ~ 110°F.


Kit Overview




Hardware Bag Overview



Hardware Kit Total
~~
 2/





of the brackets.

N O T E

